QP Code: 3363

(3 Hours)

Total Marks :80

- N.B.: (1) Questions No. 1 is compulsory.
 - (2) Solve any three questions out of remaining questions.
 - (3) Assume suitable data if required and mention it clearly.
- 1. Answer the following :-
 - (a) What are the objectives of quality control.
 - (b) Differentiate between precision and accuracy.
 - (c) Explain the concept of waviness and Roughness
 - (d) Compare pneumatic and Mechanical Comparators
- (a) A hole and shaft assembly designed as H7_p5, having nominal diameter 28 mm is being manufactured. The gauges for compound inspection are proposed on the basis of fallowing information
 - (i) 28 H 7 has upper deviation of 21 microns.
 - (ii) 28 p5 has fundamental deviation of + 22 microns and tolerance of 9 micron.
 - (iii) H = 4 $H_1 = 2.5$
 - (iv) Y = 3 Y = 2.5
 - (v) Z=3 $Z_1=1.5$ (All with std. Units)

Show dispersion of tolerance on gauges.

- (b) Define and classify various types of cost of quality with suitable examples. 10
- 3. (a) Define and indicate following gear tooth parameter on an involute tooth profile sketch:
 - (i) Base pitch
 - (ii) Root Diameter
 - (iii) Working depth tooth
 - (iv) Dedendum
 - (v) P.C.D.
 - (b) Explain P and nP charts with their applications

10

- 4. (a) With the help of graphical presentation explain following parameters used in surface texure measurement.
 - (i) R
- (ii) F
- (m) R,
- (iv) Sampling length

(b) What is best wire size? Explain three wire method used in thread measurement. 10

JP-Con. 9652-15.

[TURN OVER]

- 5. (a) Explain the phenomenon of interference of light. Explain how it can be applied in flatness measurement of surface.
 - (b) Following data gives details of quality control with respect to weight of certain object:

Weight required = 500 grams

Tolerence ±3 grams

Porcess study details = 20 sample of size 5

$$\sum \overline{x} = 9960$$
, $\sum R = 100$

Draw control chart and comment on process capability.

(For subgroup size of 5, Az = 0.58, D4 = 2.11, D3 = 0)

- 6. (a) Explain with neat sketch working of Tool marker's microscope.
 - (b) Define following terms in SQC
 - (i) LTPD
 - (ii) AQL
 - (iii) Consumers Risk
 - (iv) Producer Risk.

JP-Con. 9652-15.

10

10