

QP Code: 6302

[ Total Marks: 80 ]

(03 Hours)

- N.B: (1) Question No. 1 is compulsory
  - (2) Attempt any threequestions out of the remaining five questions.
  - (3) Assume suitable data wherever necessary.
  - (4) Figures to the right indicate full marks.
- Q.1 (a) For the component shown in Fig. 1 which is manufactured in progressive die.

  (i) Calculate economic strip layout considering size 400 mm x 1200 mm x 2
  - mm thick. Stock material is mild steel with 400 N/mm² shear strength. 4
  - (ii) Calculate cutting load and recommend suitable press.
  - (iii) Draw Sectional Front View and Top View of die showing BOM. 8




Figure 1

Note:

All Dimensions are in 'mm'

NOT TO SCALE

- (b) Compare TIG welding with Seam welding
- (a) Explain GMAW (MIG) welding with its advantages and limitations
- (b) With the help of neat sketch, explain the terminology of press tool elements.
- (c) Explain the defects in deep drawing operation. Give its remedies.
- Q.3 (a) Give the design steps of Drawing dies and comment on
  - Inter-stage annealing for multiple drawing operations.
  - (b) Define Welding. Classify different welding processes.
  - (c) Compare forming operations and cutting operations in press working

[Turn Over

6

8

6

MD-Con.8405-15.

Q.2

Q.4	(a)	Explain the terminology of bending operation with neat labelled diagram  What is V-Bending and Edge Bending operation?	8
	(b)	Define Bending Allowance and spring-back in bending.	6
	(0)	Discuss methods of reducing springback.	
	(c)	Write short notes on: Materials for Press Working components and hardness.	6
Q.5	Diffe	erentiate the following (any 4)	20
	(a)	Piercing and Blanking operation.	
	(b)	Pressure Welding and Non-Pressure Welding	
	(c).	SAW welding and SMAW welding	
#	(d)	Drawing force and Blank holding Force in Drawing operation	
	(e)	Blanking and Fine Blanking	
	(f)	OBI press and Press Brake	
Q.6	Write Short Notes of the following (any 4)		20
	(a)	Types of Welded Joints and applications	
	(b)	Methods of reducing forces in press working	
	(c)	Shut Height of Press and die	
	(d)	Types of shearingdies and die-sets	
	(e)	Feeding mechanism of blank / stock in presses	
	(f)	Fixed Stripper and movable Stripper plate.	