Q. P. Code: 547702

Electronic Instruments & oreasurements.

(3 Hours)

Total: 80

| N.B. | 1) | Question No.1 is compulsory. | |
|------|------------------|--|----------|
| | 2) | The state of the s | |
| | | | - 5- 11- |
| 1) | Attempt any four | | |
| | a) | Define transducer. List different types of transducers. | 0 |
| | b) | Draw Schering Bridge and list applications. | Oliva |
| | c) | Draw a neat labeled McLeod Gauge system diagram | 5 5 |
| | d) | Explain measuring principle of 'Q' meter and list applications | 6 |
| | e) | Explain level measurement using differential pressure technique | |
| | | Solution of the state of the st | 5 |
| 2) | a) | Explain in detail different types of errors in measurement system | 40 |
| | b) | Explain FET type electronic voltmeter with neat circuit diagram. | 10 |
| | | | 10 |
| 3) | a) | Discuss static and dynamic characteristics of instruments with | 40 |
| | | importance of each parameter under consideration. | 10 |
| | b) | Explain in detail Dead Weight Testing with neat labelled diagram | 40 |
| | | S. O. T. | 10 |
| 4) | a) | Explain LVDT with neat labeled diagram | 10 |
| | b) | Draw and explain Kelvin's Double Bridge for unknown resistance | 10 |
| | | measurement | 10 |
| | | | |
| 5) | a) | Explain single channel and multichannel data acquisition system | 10 |
| | | with neat labeled separate block diagrams. | 10 |
| | b) | Draw block diagram of CRO. and DSO. List important features and | 1 10 |
| | | applications of DSQ 6 | 10 - |
| | | R | |
| 6) | | ort note on (any four) | 20 |
| | a) | Selection criteria of transducers | 20 |
| | b) | Strain Gauges | |
| | c) | Turbine flow meter | |
| | d) | Thermocouples | |
| | e) | Megohm bridge for high resistance measurement | |
| | la! | | |
| | 11/1 | | |